A MODIFICATION ONLY - DOES NOT COMMUNICATE

83480A-03

<u>SERVICE NOTE</u>

Supersedes: NONE

83480A Digital Communications Analyzer

Serial Numbers: [0000A00000 / 9999Z99999]

Complex replacement for E2602-64101

Parts Required:

P/N Description Qty.

86100-60024 Hole Plug 1 6960-0001 Hole Plug 1

Situation:

E2602-64101 Hole Plug is no longer available

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: BMH PRODUCT LINE: 8F

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.

December 20, 2005



Page 2 of 2 83480A-03

Solution/Action:

The hole plug that helps stabilize the time base adjustment, p/n E2602-64101, is no longer available. This plug is important to maintain the timebase specifications and stability. To replace the part, assemble a replacement from the new plug for the 86100 series and a metal plug.

Order 1 each,

86100-60024 Hole Plug 6960-0001 Hole Plug

Cut the plastic cap off of 86100-60024 Hole Plug, leaving the foam \sim 2.5 cm long. Insert this foam into 6960-0001 Hole Plug.