

## S E R V I C E N O T E

SUPERSEDES: None

**8517B S-Parameter Test Set**

Serial Numbers: 0000A00000 / 9999Z99999

**Test Set Option 002 deletion****Duplicate Service Notes:**

8517A-02

8517B-02

**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

Part No.	Qty.	Description
08517-60046	1	Service Kit

**Situation:**

8517B Test Set option 002 deletes the attenuators and the bias TEEs.

**Solution/Action:**

8517B Test Set with option 002 can be retrofitted into standard test set by installing the service kit 08517-60046. The kit contains the necessary parts and instructions to install the kit properly.

DATE: January 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hour		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: Product's Support Life		
AUTHOR: JZ	ENTITY: 5340	ADDITIONAL INFORMATION:			