

S E R V I C E N O T E

Supersedes:
NONE

HP MODEL 8558B SPECTRUM ANALYZER
ALL SERIALS
BANDWIDTH FILTER BOARD REPLACEMENT

The A11 and A13 Bandwidth Filter boards are identical and may be used in either the A11 or A13 position. Do not interchange the Filter boards after the filters have been aligned.

New or exchange Bandwidth Filter boards will have two crystals installed and two additional crystals attached. The two extra crystals must be installed on the other Bandwidth Filter board in the 8558B.

Bandwidth Filter crystals are made as a matched set and must always be installed in matched sets.

The Bandwidth Filter alignment procedure in Section 5 of the Operating and Service Manual must be performed whenever crystals or boards are changed.

JRB/KS/WN

1/74-45



For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.

Printed in U.S.A.