

S E R V I C E N O T E

Supersedes:

NONE

HP MODEL 8558B SPECTRUM ANALYZER

Serials Prefixed 1334A and Below

NEW FRONT PANEL LATCH HOUSING

The Latch Housing has been changed from a machined part, HP Part Number 08558-20091, to a plastic molded part, HP Part Number 08558-40015. The Latch Housings are not interchangeable. The machined Latch Housing is available for replacement use.

Should it ever be necessary to replace the 8558B front sub-panel, for serials prefixed 1334A and below, the Latch Housing must also be replaced using the plastic Latch Housing, HP Part Number 08558-40015.

All newer 8558B's must also have the plastic Latch Housing, HP Part Number 08558-40015, replaced whenever the front sub-panel, HP Part Number 08558-00002, is replaced. This is due to loss of strength in the plastic threads when reused.

JRB/KS/WO

2/74-45

HEWLETT  PACKARD

For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.

Printed in U.S.A.