

S E R V I C E N O T E 8566B-11B

SUPERSEDES: 8566B-11A

HP 8566B Spectrum Analyzers
HP 8567A Spectrum Analyzers
HP 8568B Spectrum Analyzers

Serial Numbers:

0000A00000/9999A99999

Duplicate Service Notes:

8566B-11B

8567A-01A

8568B-11B

A15 CONTROLLER ASSEMBLY FIRMWARE REPLACEMENT KIT

To Be Performed By: Customer or HP-Qualified Personnel

Parts Required:

Firmware Replacement Kit (See Table 1 for part numbers and contents.)

PAL HP part number 85660-80070 (See NOTE)

DATE: 13 November 1989

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		MODIFICATION AVAILABLE	
ACTION CATEGORY: AGREEABLE TIME		☒ PERFORMANCE ENHANCEMENT ☐ SERVICEABILITY/RELIABILITY ENHANCEMENT	
LOCATION CATEGORY: ☒ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ HP LOCATION		AVAILABLE UNTIL: Support Life	
AUTHOR: BF ENTITY: 5300		ADDITIONAL INFORMATION: Installation Note 5958-7130	

©1989 HEWLETT-PACKARD COMPANY
 PRINTED IN U.S.A.



8566B-11B

NOTE

The PAL is needed for firmware upgrade of HP 8568B Spectrum Analyzers with serial numbers 0000A00000/2445A00971 or HP 8568A Spectrum Analyzers that have been upgraded to an HP 8568B with the HP 8568AB Retrofit Kit (formerly HP 8568A + 01K) with serial numbers 0000A00000/2426A00316.

Situation:

From time to time, firmware is changed to correct bugs or add enhancements.

Solution/Action:

Firmware Replacement Kits are available to upgrade your spectrum analyzer. The Firmware Replacement Kits contain the latest version of firmware.

Table 1. Firmware Replacement Kits			
Kit Contents	HP8566B 085660-60270	HP 8567A 085670-60009	HP 8568B 085680-60197
Date Code	10.10.89	7.4.87	7.4.87
A15U37 EPROM	85660-80185	85670-80019	85680-80113
A15U38 EPROM	85660-80187	85670-80021	85680-80115
A15U39 EPROM	85660-80186	85670-80020	85680-80114
A15U40 EPROM	85660-80188	85670-80022	85680-80116