

Supersedes:

None

HP MODEL 8565A AND 8569A/B SPECTRUM ANALYZERS**All Serials****FRONT PANEL CONTROL SWITCH BOARD ASSEMBLY**

There is now a sub-assembly available for repair of the Front Panel Control Assembly A2. The complete A2 assembly is sometimes ordered for repair of the Frequency Span/Division or Reference Level Switch Assemblies. Since the A2 assembly includes the front panel, knobs, and tuning switch assembly, it is fairly expensive.

There is a lower-level assembly available for this part which includes A2A1, A2A4, and A2A6. It is a complete switch assembly for the Frequency Span/Division and Reference Level switches, at less than half the cost of the full front-panel assembly. The correct HP Part Number and some reference information is indicated below.

For	A2 Part Number	Use Switch Assembly
8565A	08565-60120 08565-60001	08565-60126
8569A	08569-60036 08569-60063	08565-60126
8569B	08569-60078 08569-60063	08569-60116

I/OF/WN

7/84-53/MLG



FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE or East (201) 265-5000 • Midwest (312) 255-9800 • South (404) 955-1500 • West (213) 970-7500 or (415) 968-9200 OR WRITE, Hewlett-Packard, 1820 Embarcadero, Palo Alto, California 94303. IN EUROPE, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE OR WRITE, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 Meyrin 2-Geneva, Switzerland. IN JAPAN, Yokogawa-Hewlett-Packard Ltd., 1-27-15, Yabe Sagami-hara City, Kanagawa Prefecture, Japan 229.