

DAYTON

ELLIS DONNIE SERVICE NOTE

8690B-9

Supersedes:

NONE

**HP MODEL 8690B SWEEP OSCILLATOR**

**Serial Prefix 1202A and Below**

**RECOMMENDED REPLACEMENT FOR A8C4 and A8C5**

The recommended replacement for A8C4 and A8C5 in all HP 8690B Sweep Oscillators with serial prefix 1202A and below is HP Part Number 0160-4051. The 0160-4051 has the same capacitance value and is a direct replacement. The capacitor supports on the printed circuit board are not needed for the replacement capacitor and can be discarded.

No recalibration is necessary.

Correct your 8690B Operating and Service Manual Parts List to reflect the above change.

AS/RH/WO

3/74-45



For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.

Printed in U.S.A.