

S E R V I C E N O T E

SUPERSEDES: NONE

E1650A Series 90 Modular SONET/SDN Analyzer**Serial Numbers:** 0000A00000 / 9999Z99999**Potential Command Module hang-up problem.****Situation:**

A hang-up condition can occur in these systems when E1683/4A modules are added to the system due to an E1405A/B Command Module problem. Future module designs could also show up this condition.

Solution/Action:

Implement Service Note E1405A/B-01 to all E1405B modules in the quoted serial range. All systems where E1683/4A are to be installed must have updated Command modules. All Command Modules of other systems should be updated at a convenient time.

Note:

E1405A/B modules serial 3126A01557 and above will already have this modification, also all E1650A systems shipped after April 24, 1992 will have had their E1405B Command Modules modified. E1405B modules with serial below 3126A01557 will be labelled (E1405A/B-01) near the rear connector if Service Note E1405A/B-01 has been implemented.

DATE: 24 August 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

DG

1400

ADDITIONAL INFORMATION:

Refer to Service Note E1405A/B-01

