

## S E R V I C E N O T E

SUPERSEDES: NONE

**E1652A Series 90 Modular SONET/SDH Analyzer****Serial Numbers:** 0000A00000 / 9999Z99999**Potential Command Module hang-up problem****Situation:**

A hang-up condition can occur in these systems when E1683/4A modules are added to the system due to a E1405A/B Command Module problem. Future module designs could also show up this condition.

**Solution:**

Implement service note E1405A/B-01 to all E1405B modules in the quoted serial range. All systems where the E1683/4A are to be installed must have updated Command Modules. All Command modules of other systems should be updated at a convenient time.

**Note**

E1405A/B modules serial 3216A01557 and above will already have this modification, also E1652A systems shipped after April 24, 1992 will have had their E1405B Command modules modified. E1405B modules with serial below 3126A01557 will be labelled. (E1405A/B-01) near the rear connector if service note E1405A/B-01 has been implemented.

DATE: 24 August 1992

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

<b>AUTHOR:</b>  DG	<b>ENTITY:</b>  1400	<b>ADDITIONAL INFORMATION:</b>
--------------------------	----------------------------	--------------------------------