

S E R V I C E N O T E

SUPERSEDES: None

E1672A SONET/SDH Transport Overhead Generator**Serial Numbers:** AU32000000 / AU32022257**Levels on Trig output not to TTL spec when loaded with 50 ohms****Situation:**

On instruments with the above serial numbers the following symptoms may be apparent:

Trigger levels outside recommended TTL specs when loaded at 50 ohms.

Solution/Action:

Replace resistor R5 with 51.1 ohms resistor

Parts Required:

Part number 0757-0394 Resistor, 51.1 ohms

DATE: 06 December 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 1.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 06 December 1995
AUTHOR: DH	ENTITY: Y900	ADDITIONAL INFORMATION:	