

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E1852B-01A

S E R V I C E N O T E

Supersedes:
E1852B-01

E1852B Bluetooth Test Set

Serial Numbers: DK00000000 / DK99999999

Test Re-instated In The Performance Verification Procedure

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: FC PRODUCT LINE: PN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



Agilent Technologies

May 8, 2006

Situation:

The RF Generator Frequency Accuracy test was removed from the E1852B performance verification procedure in November 2005. Even though RF Generator Frequency Accuracy is not a guaranteed specification, the decision to remove this test has been reversed for the following reasons:

1. Customers still expect to see this test in the performance verification procedure.
2. Removing this test reduced the likelihood of detecting other frequency accuracy problems.
3. Agilent Service Centers now have the capability to adjust (rather than repair) units that fail this test.

Solution/Action:

The RF Generator Frequency Accuracy test will be re-instated in the E1852B performance verification procedure at the end of April 2006.