

S E R V I C E N O T E

SUPERSEDES: None

4073A Ultra Advanced Parametric Tester

Serial Numbers:

- E3101A JP20D00301/JP99Z99999
- E3102A JP00A00000/JP99Z99999
- E3102L JP00A00000/JP99Z99999
- E3103A JP00A00000/JP99Z99999

Rear door may rub off paint coat of PDU main switch.

Duplicate Service Notes:

- E3101A-15
- E3102A-03
- E3103A-02

To Be Performed By: Agilent-Qualified Personnel

Parts Required: None

Situation:

If the floor of 4070 installation site is uneven and the cabinet is distorted, the rear door may rub off the paint coat of PDU main switch.

Solution / Action:

Raise the rear left corner (rear door hinge side) by lowering the leveling foot.

DATE: January 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: SY	ENTITY: 3300	ADDITIONAL INFORMATION:

