

E36313A-02

Modification Recommended Service Note

Supersedes:
NONE

E36313A 160W Triple Output Power Supply

Serial Numbers: MY58100000/MY58491719

The Problem – Compliance to EMC IEC61000-4-3 standard requires a ferrite core.

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hours		
LOCATION	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input checked="" type="checkbox"/> SCRAP	PARTS:	<input checked="" type="checkbox"/> SCRAP
	<input type="checkbox"/> SERVICE CENTER		<input type="checkbox"/> SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	1 st Feb 2020	NO CHARGE AVAILABLE UNTIL:	1 st Feb 2020		
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	SP		
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	KHEW		

ADDITIONAL INFORMATION:

Situation:

Compliance to EMC IEC61000-4-3 standard requires a ferrite core at rear channel 1 output. The ferrite core does not affect the functionality and performance of this product.

Solution/Action:

For the affected serial numbers, a ferrite core with installation instructions will be provided. Please download and complete this [form](#) and email to power.servicenote@keysight.com to obtain the kit at no cost.

Revision History:

Date	Service Note Revision	Author	Reason for Change
24 JAN 2019	01	KHEW	As Published