

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**E4435B-06B**

# **S E R V I C E                      N O T E**

Supersedes:  
E4435B-06A

**E4435B with options UNB or H99**

**Serial Numbers: [0000A00000 / 9999Z99999]**

**Mechanical attenuator, part number 33322-60014, with serial numbers less than 06400 (Made in USA) used in the identified products is susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions.**

**Parts Required:**

| <b>P/N</b>  | <b>Description</b>    | <b>Qty.</b> |
|-------------|-----------------------|-------------|
| 33322-60014 | Mechanical Attenuator | 1           |

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:

### **INFORMATION ONLY**

AUTHOR: HLU      PRODUCT LINE: 15

**ADDITIONAL INFORMATION:**

33322-60014 assemblies are to be provided at no cost until 1AUG2006

© AGILENT TECHNOLOGIES, INC. 2005  
PRINTED IN U.S.A.



July 18, 2005

**Situation:**

**Mechanical attenuator, part number 33322-60014, with serial numbers less than 06400 (Made in USA) used in the identified products is susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions.**

**Solution/Action:**

**Mechanical attenuators, part number 33322-60014, will be provided for repair of products with less than 3 million attenuator cycles. Customers are responsible for labor and calibration charges.**