

E4435B-12

S E R V I C E N O T E

Supersedes:
NONE

ESG “B” Signal Generator E4435B

Serial Numbers: All units

Output amplitude spikes at 396MHz and 628MHz of 2dB during step sweep mode

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: PY	PRODUCT LINE: 15
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

August 4, 2008

Rev. 15



Agilent Technologies

Situation:

In step mode in range of 395MHz and 630MHz spikes of approximately 2dB amplitude can be observed using a spectrum analyzer. The spikes are at the switch points of the low pass filters in the Frac-N assembly. All ESG-AP and ESG-DP models are affected.

Solution/Action:

This is a firmware defect. ESG-AP and ESG-DP models are discontinued and the End of Support is 1-Nov-2010. No further firmware changes are anticipated to the current firmware B.03.86. The spikes at 396MHz and 628MHz are a characteristic of the design and cannot be eliminated, no repair is needed.