E4980A-07

<u>SERVICE NOTE</u>

Supersedes: NONE

E4980A Precision LCR Meter 20Hz to 2MHz

Serial Numbers: ALL

E4980A A1 PCA Motherboard Assembly Firmware Compatibility Information

Parts Required:

P/N Description Qty.

E4980-66641 Printed Circuit Board Assembly, Pb-free, Mother Board 1

ADMINISTRATIVE INFORMATION

INFORMATION ONLY

[X] Calibration Required
[Mathematical Product Line: WN AUTHOR: LS

ADDITIONAL INFORMATION: This service note communicates the firmware revision requirement for new A1Motherboard PCA

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



October 1, 2013

Rev. 21 Page 1 of 2

Page 2 of 2 E4980A-07

Situation:

A1 Board PCA E4980A Motherboard will be changed as follows.

Current: E4980-66601 New: E4980-66641

Firmware 2.xx and below will not work with new A1 module (E4980-66641)

Solution/Action:

Please refer to the following table on the recommended firmware revision for the respective A1 PCAs.

A1 Doord DCA DN	Firmware rev. 2.xx and	Firmware rev. 3.xx and
A1 Board PCA PN	below	above
E4980-66601	OK	OK
E4980-66641	NOT COMPATIBLE	OK

Revision History:

Revision Number	Date	Author	Reason For Change
1.0	30 Sept 2013	LS	As published