F4981A-09A

Modification Recommended Service Note

Supersedes: E4981A-09

E4981A Capacitance Meter

Serial Numbers: See below

D value deviation issue

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE [X] AGREEABLE TIME	STANDARDS LABOR: 2.0 Hours			
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [X] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT			
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 30-June-2020			
[X] Calibration Required [[]] Calibration NOT Required		PRODUCT LINE: WN AUTHOR: jm			

ADDITIONAL INFORMATION:



Situation:

D value deviation is found while checking D value with 16380A/C.

Solution/Action:

Perform full adjustment then perform Performance Test. Provide CoC and Measurement Report to customer.

Serial Number list:

MY48308198	MY48308199	MY48308201	MY48308204	MY48308205	MY48308222	MY48308246	MY48308247
MY48308249	MY48308250	MY48308445	MY48308482	MY48308484	MY48308487	MY48308492	MY48308971
MY48308972	MY48308977	MY48308980	MY48308983	MY48308988	MY48309001	MY48309005	MY48309011

Revision History:

Date	Service Note Revision	Author	Reason for Change
05 Jun 2019	E4981A-09	Jun Maruo	As Published
11 Jun 2019	E4981A-09A	Jun Maruo	Added H in house
11 Juli 2019	E4981A-U9A	Jun Maruo	Added Hill House