E5071A-09

# <u>SERVICE NOTE</u>

Supersedes: None

E5071A ENA Series Network Analyzer, 300 kHz to 8.5 GHz

Serial Numbers: [0000A00000 / 9999Z99999]

Part Number Change for the CPU memory

Parts Required: See solution

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## **INFORMATION ONLY**

AUTHOR: jm PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.

.... A

**Agilent Technologies** 

February 21, 2007

Page 2 of 2 E5071A-09

#### **Situation:**

Part numbers for the CPU memory have been changed.

#### **Solution/Action:**

### **Parts Required**

| Old P/N   | New P/N   | Description      |
|-----------|-----------|------------------|
| 1818-8150 | 5188-4433 | SYNC-DIMM 16Mx64 |
| 1818-8783 | 5188-4434 | SYNC-DIMM 32Mx64 |

<sup>-</sup> End of Document -