

E5071C-17**S E R V I C E N O T E**Supersedes:
NONE**E5071C - ENA Series Network Analyzer, 9 kHz to 20 GHz****Serial Numbers:** See list at end of this service note**Receiver board failure****Parts Required for Option 240, 260, 280, 440, 460 or 480:**

P/N	Description	Qty.
E5071-62282	Tested Receiver Module (Without Bias Tee)	2 to 4

Parts Required for Option 245, 265, 285, 445, 465 or 485:

P/N	Description	Qty.
E5071-62292	Tested Receiver Module (With Bias Tee)	2 to 4

Parts Required for Option 2D5, 2K5, 4D5 or 4K5:

P/N	Description	Qty.
E5071-62097	Tested Receiver Module	2 to 4

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS LABOR: 4.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☒ ON-SITE ☒ SERVICE CENTER ☐ CHANNEL PARTNER	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS: ☒ RETURN ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
☒ Calibration Required ☐ Calibration NOT Required		NO CHARGE AVAILABLE UNTIL: 30-Sep-2015 PRODUCT LINE: WN AUTHOR: jm	
ADDITIONAL INFORMATION:			



Situation:

Some network analyzers may need the receiver board replaced.

Solution/Action:

If the network analyzer has one of the serial numbers listed below and one Receiver Board fails (for any fail mode), all the receiver boards in that instrument should be replaced under factory warranty. This will be valid until 30-September-2015.

Serial-numbers:

SERIAL NUMBER	SERIAL NUMBER	SERIAL NUMBER	SERIAL NUMBER	SERIAL NUMBER
MY46103174	MY46103127	MY46105635	MY46101961	MY46106251
MY46103315	MY46103128	MY46105740	MY46105389	MY46106253
MY46103497	MY46103129	MY46105743	MY46106295	MY46106269
MY46104399	MY46103130	MY46105999	MY46103070	MY46106279
MY46104772	MY46103131	MY46106258	MY46103082	MY46106286
MY46105465	MY46103132	MY46106259	MY46103244	MY46106287
MY46105474	MY46103133	MY46106261	MY46103255	MY46106382
MY46105501	MY46103134	MY46106292	MY46103389	MY46106383
MY46105619	MY46103137	MY46106293	MY46103431	MY46106387
MY46105665	MY46103138	MY46106296	MY46103458	MY46106388
MY46105930	MY46103143	MY46106297	MY46103947	MY46106399
MY46105939	MY46103170	MY46106342	MY46103952	MY46106422
MY46105948	MY46103182	MY46106346	MY46104514	MY46106423
MY46105973	MY46103901	MY46106349	MY46104588	MY46106425
MY46105974	MY46104062	MY46106350	MY46104591	MY46106469
MY46105979	MY46104063	MY46106352	MY46104899	MY46106478
MY46105980	MY46104065	MY46106355	MY46105049	MY46106713
MY46106017	MY46104095	MY46106357	MY46105064	MY46106799
MY46106291	MY46104179	MY46106376	MY46105065	MY46106800
MY46106320	MY46104215	MY46106381	MY46105348	MY46106827
MY46106356	MY46104218	MY46106407	MY46105531	MY46105576
MY46106612	MY46104227	MY46106951	MY46105535	
MY46103181	MY46104256	MY46106954	MY46105543	
MY46103183	MY46104258		MY46105572	
MY46104088	MY46104263		MY46106040	
MY46104259	MY46104266		MY46106041	
MY46104261	MY46104518		MY46106042	
MY46105428	MY46104771		MY46106043	
MY46105517	MY46105455		MY46106047	
MY46105590	MY46105521		MY46106103	
MY46105609	MY46105618		MY46106220	
MY46106940	MY46105632		MY46106239	
MY46106952	MY46105634		MY46106243	
			MY46106244	
			MY46106246	
			MY46106247	
			MY46106248	
			MY46106249	
			MY46106250	