A MODIFICATION ONLY - DOES NOT COMMUNICATE

E5100A-34B

<u>SERVICE NOTE</u>

Supersedes: E5100A-34A

Agilent E5100A Network Analyzer

Serial Numbers: See Solution / Action

Part Number Changes for Power Supply and Switch Parts

Parts Required: See Solution / Action

To Be Performed By: Agilent-Qualified Personnel

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DK PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004 PRINTED IN U.S.A.



August 11, 2004

Page 2 of 2 E5100A-34B

Situation:

A power supply assembly and related service parts were obsoleted and replaced with new service parts.

Solution/Action:

When replacing any of the parts listed in Table 1 or Table 3, order appropriate parts as below, depending on the serial number of the E5100A. Refer to Chapter 13, Figure 13-8 and Figure 13-37 of E5100A/B service manual (PN: E5100-90130) for a detail assemble procedure.

WARNING!

<u>Do not use old service parts listed in Table 1 and Table 3 in repair. Also do not disassemble new power supply assembly (E5100-65005). These actions have a risk to cause an electric shock because of a different cable assignment with a compatible connector.</u>

Serial Number: JP5KC03371 and below

When replacing any of the parts listed in Table 1, replace all parts listed in Table 1 with the new parts shown in Table 2. E5100-65005 includes replacement parts for E5100-65002, E5100-61632, and E5100-61631 or E5100-61642.

Table 1 Old Parts (obsoleted)

Part Number	Qty.	Manual Description
E5100-65002	1	PS 130W POWER SUPPLY
E5100-61632	1	WIRE ASSY LWQ130
E5100-61631 or E5100-61642	1	WIRE ASSY PRM
E5100-01202	1	ANGLE SW
0515-0999	2	M2.5X0.45 L=6 FL

Table 2 New Replacement Parts for JP5KC03371 and below

Part Number	Qty.	CPL Description
E5100-65005	1	SVC power supply assy
E5100-01205	1	ANGLE
0515-0914	2	SCREW-MACHINE; M3.0 X 0.50; 6 MM LONG

Serial Number: JP5KC03372 and above, MY405xxxxx

When replacing any of the parts listed in Table 3, replace all parts listed in Table 3 with the new parts shown in Table 4. E5100-65005 includes replacement parts for E5100-65002, E5100-61632, and E5100-61631 or E5100-61642.

Table 3 Old Parts (obsoleted)

Part Number	Qty.	Manual Description
E5100-65002	1	PS 130W POWER SUPPLY
E5100-61632	1	WIRE ASSY LWQ130
E5100-61631 or E5100-61642	1	WIRE ASSY PRM

Table 4 New Replacement Part for JP5KC03372 and above, and MY405xxxxx

Part Number	Qty.	CPL Description
E5100-65005	1	SVC power supply assy