

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**E6392B-05**

# S E R V I C E                      N O T E

Supersedes:  
None

## Agilent Technologies E6392B GSM MS Test Set

**Serial Numbers:** [0000A00000 / 9999Z99999]

**Revision B.03.03 firmware has new capability and corrects GPRS attachment and connection problem**

**Parts Required:**

P/N	Description	Qty.
-----	-------------	------

None

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: S.A.      PRODUCT LINE: BJ

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



**Agilent Technologies**

October 25, 2002

**Situation:**

When customer measure some mobile phone with E6392B opt 040 GPRS mode, sometimes GPRS attachment and connection doesn't work well.

**Solution/Action:**

Update the firmware to Rev B.03.03.

Also Rev B.03.03 firmware has the new capability called "6ch path loss compensation in Auto Test".