

E6680A-03

Modification Recommended Service Note

Supersedes:
NONE

E6680A Wireless Test Set

Serial Numbers: MY60210001 - MY61323030

The Problem – Units are missing the input level warning label

Parts Required:

P/N	Description	Qty.
E6680-80001	Label-Warning Maximum Power and Voltage	1

ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.1 Hours		
LOCATION	X SERVICE CENTER	SERVICE:	<input type="checkbox"/> RETURN	USED	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	<input type="checkbox"/> CHANNEL PARTNERS		<input checked="" type="checkbox"/> SEE TEXT		<input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	January 2025		
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	13		
	X Calibration NOT Required	AUTHOR:	MW		

ADDITIONAL INFORMATION:

Install missing label on instrument dress panel (no scrap)

Situation:

E6680A instruments were shipped without the input level warning label on the dress panel. There is not a safety issue to the customer. The label is a warning to the input levels that will damage the instrument.

Solution/Action:

Place E6680-80001 label on dress panel



Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Nov 2022	01	Michael Woichik	As Published