

E8361C-03

S E R V I C E N O T E

Supersedes:
None

E8361C PNA Microwave Network Analyzers

Serial Numbers: US000000000/US999999999 (All)

E8361A and E8361C Automated Source Adjustment software needs to have greater functionality. Until this functionality is implemented in March 2009, any source-chain component replacement and corresponding calibration process must be done in the Agilent factory.

Parts Required: None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: MR	PRODUCT LINE: WN
ADDITIONAL INFORMATION: Affected PNA models: E8361A/C. Service Note History: E8361C-03 released Oct 24, 2008.	

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

October 27, 2008

Rev. 15



Agilent Technologies

Situation:

E8361A and E8361C Automated Source Adjustment software needs to have greater functionality before it can be used by Service Center personnel or customers.

Solution/Action:

In March 2009, a new version of the E8361A/C Automated Source Adjustment software will be released that will have greater functionality. In the meantime, any source-chain component replacement (see below) and corresponding calibration process must be done in the Agilent factory.

Components in the Source Chain:

P/N	Description
E8361-60002 -and- E8361-69002	Source 20 Assembly
5087-7130 -and- 5087-6130	SOMA 50
5087-7249	SOMA 70