

S E R V I C E N O T E

SUPERSEDES: None

**J2301B Internet Advisor**

**Serial Numbers:** US35351074 US35351228 US35351241  
 US35351222 US35351229 US35351258  
 US35351225 US35351230  
 US35351227 US35351240

**Undercradle interface card Long Leads short to chassis.**

**Parts Required:** J2295-66502 Undercradle Adapter

**Situation:**

The J2295-66502 Undercradle Adapter interface card used to connect an undercradle may short to the chassis if the J2295-66502 feedthrough leads are not cut. The leads must be cut flush with the PC Board.

**Solution:**

Replace bad assembly with J2295-66502.

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AUTHOR: NB	ENTITY: 3801	AGILENT RESPONSIBLE UNTIL: June 1998	
		ADDITIONAL INFORMATION:	