

S E R V I C E N O T E

SUPERSEDES: None

**J2522B Internet Advisor LAN**

**Serial Numbers:** US3540101 / US35359999

**PAW Link (Mouse Pointer) bad date code**

**Duplicate Service Notes:**

J2301B-02 Serial Numbers: US35340101 / 35359999

J2302B-02 Serial Numbers: US35340101 / 35359999

J2523B-03 Serial Numbers: US35340101 / 35359999

**Parts Required:** F1049-60901 PAW Link

**Situation:**

The PAW Link with date code 9516 or earlier has a design problem whereas the part can become intermittent or inoperative. The date code can be viewed by opening the PAW Link (mouse) and looking at the bottom inside to see the date code.

**Solution/Action:**

1. Remove the PAW link bu pulling the mouse slowly but firmly from the side of the chassis.

*Continued*

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor Hour		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1998			
AUTHOR: RM	ENTITY: 3801	ADDITIONAL INFORMATION:			

2. Open the PAW link and check the date code to ensure that it is not date code 9516 or earlier. If greater than, do not replace.
3. Replace all non-conforming PAW links F1049-60901. Replace with new part number 5061-4390.

