A MODIFICATION ONLY - DOES NOT COMMUNICATE

SN J6816A-02

<u>SERVICE NOTE</u>

Supersedes: NONE

J6816A E1/T1 (RJ45/48C & DB9 connectors) LIM

Serial Numbers: [0000A00000 / 9999Z99999]

Due to the low volume sales of the A version of this product, it was determined that support assemblies for would not be set up with GTLS. Should the PCA's need to be replaced please use the equivalent B model boards. New (5067-0328) Exchange (5067-0084)

Parts Required: P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE	ECLASSIFICATION:	
INFORMATION ONLY		
AUTHOR: DM	PRODUCT LINE: 2J	
ADDITIONAL INI	NFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2003 PRINTED IN U.S.A.



July 18, 2003