

N1911A-08A

Modification Recommended Service Note

Supersedes:
N1911A-08

N1911A P-Series Single Channel Power Meter

Serial Numbers: MY57200021 MY57220003 MY57220008 MY57250002 MY57250004
MY57170014 MY57200004 MY57200007 MY57200009 MY57200010 MY57200012
MY57200014 MY57200019 MY57200020 MY57220002 MY57220004 MY57220005
MY57220006 MY57230002 MY57230003 MY57230006 MY57230007 MY57230008
MY57150002 MY57150003 MY57150004 MY57150005 MY57150006 MY57150007
MY57150008 MY57150009 MY57150010 MY57150011 MY57170004 MY57170005
MY57170006 MY57170007 MY57170008 MY57170009 MY57170010 MY57170011
MY57170012 MY57170013 MY57200005 MY57200006 MY57200008 MY57200011
MY57200013 MY57200015 MY57200016 MY57200017 SG57170003 SG57170004

Loosen power reference connector assembly

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	X AGREEABLE TIME	LABOR:	2 Hours
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP
	X SERVICE CENTER		X SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	01-Oct-2018
	X Calibration Required	PRODUCT LINE:	WN
	<input type="checkbox"/> Calibration NOT Required	AUTHOR:	CKN

ADDITIONAL INFORMATION:

Parts Required:

P/N	Description	Qty.
N1911-61001	Calibrator Assembly – Front	1

Situation:

Keysight recently discovered a loose power reference connector assembly in the power meter which may result in a lower accuracy of the 1mW Power Reference. This may cause an additional power measurement error of up to 1.0%.

We would recommend customers to return the Power Meter model number and serial number listed above to the nearest Keysight Service Center for repair.

Solution/Action:

Please contact Keysight Technologies' Customer Contact Center at www.keysight.com/find/contactus for the recommended product modification.

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Sep 2017	01	CKN	As Published
13 Jun 2018	01A	CKN	Change the parts required to N1911-61001. To deplete N1911-61001.