

MODIFICATION RECOMMENDED

**N1913A-03A**

**S E R V I C E N O T E**

Supersedes:  
N1913A-03

**N1913A EPM Series Single-Channel Power Meter**

Serial Numbers: MY49100112, MY49100111, MY50000226 & MY50000231

**Lack of Front Sensor Input for N1913A–Option 108**

**Parts Required:**

P/N	Description	Qty.
NONE		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 2 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER – RTF <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	Product Support Life	NO CHARGE AVAILABLE UNTIL: 31 <sup>st</sup> December 2011	
AUTHOR:	LCW	PRODUCT LINE: WC	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2011  
PRINTED IN U.S.A.

July 21, 2011

Rev. 18



**Situation/ Root Cause:**

1. The N1913A option 108 should come with front and rear sensor inputs as stated in the product's User Guide.
2. However, the documented serial numbers only had the rear sensor input.
3. This service note is to notify the availability of the modification to install the missing front sensor input.
4. Meanwhile, all the new units of N1913A option 108 will come with sensor inputs in front and rear panel, front panel reference calibrator connector and 2 rear USB ports

**Solution/Action:**

1. Customer can contact Agilent's Customer Contact Center (CCC) for returning the unit to Agilent's Service Center for a factory rework.
2. CCC will arrange with Agilent's Customer Service Representative (CSR) for sending the prepaid shipping label to customer for a no-charge return to the Agilent Service Center
3. Figure 1 and figure 2 show the physical condition of the N1913A option 108 after install of the front sensor input. The sensor inputs are installed at front and rear panel of N1913A.




Figure 1

Sensor inputs are available in rear and front panel now



Figure 2

Sensor inputs are available in rear and front panel now