

Information Only Service Note

Supersedes:
NONE

N2805A Differential probe - 200 MHz 500V 5m

Serial Numbers ALL

The Problem – The supplier for the N2805A stopped being Keysight's supplier for this probe. The N2805A-FG is no longer available for support. So, this service note is to tell customers, and service centers the support part is now DP0031A-FG.

Parts Required:

| P/N | Description | Qty. |
|------------|-------------------------------------|------|
| DP0031A-FG | Probe, differential, 200 MHz, 750 V | 1 |

ADMINISTRATIVE INFORMATION

| | |
|--|--------------------|
| <input type="checkbox"/> Calibration Required | PRODUCT LINE: PL1A |
| <input checked="" type="checkbox"/> Calibration NOT Required | AUTHOR: MR |

ADDITIONAL INFORMATION:

Situation:

The supplier for the N2805A stopped being Keysight’s supplier for this probe. The N2805A-FG is no longer available for support. So, this service note is to tell customers, and service centers the support part is now DP0031A-FG.

Solution/Action:

If the N2805A part is needed to be replaced at service centers use the DP0031A-FG as the replacement part.

Revision History:

| Date | Service Note Revision | Author | Reason for Change |
|-------------|-----------------------|-------------|-------------------|
| 26 FEB 2025 | 01 | Mark Rowley | As Published |
| | | | |
| | | | |
| | | | |