

**N5225A-01**

# **S E R V I C E                      N O T E**

Supersedes:  
None

## **N5225A PNA Series Microwave Network Analyzers**

**Serial Numbers: MY51451026, MY51451027, and MY51451030**

**PNA instruments with the serial numbers listed above are being returned to Agilent so the source board(s) can be replaced, due to a possible source ALC loop oscillation.**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
5087-7342	26.5 GHz source board	1 or 2

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b> <b>INTERNAL ONLY DOCUMENT</b>	
AUTHOR: MF	PRODUCT LINE: WN
ADDITIONAL INFORMATION: Models affected: N5221A, N5222A, N5225A, and N5242A. Original service note created January 25, 2012.	

© AGILENT TECHNOLOGIES, INC. 2012  
PRINTED IN U.S.A.

February 2, 2012

Rev. 19



**Situation:**

PNA instruments with the serial numbers listed on the previous page are being returned to Agilent due to a possible source ALC loop oscillation caused by a faulty diode.

**Solution/Action:**

Replace the source board(s).