

N5230A-09**S E R V I C E N O T E**Supersedes:
none**N5230A PNA-L Series Microwave Network Analyzers****Serial Numbers:**

MY45000887, MY45000888, MY45000891, MY45001052, MY46400132, MY46400187, MY46400216,
 MY46400218, MY46400263, MY46400264, MY46400334, MY46400352, MY46400355, MY46400672,
 MY46401324, MY46401396, MY48100489

Some network analyzers may require servicing. Only serial numbers listed above are affected.

Parts Required:

(Refer to Service Note N5230A-08)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	ON SPECIFIED FAILURE	STANDARDS LABOR: 6.0 Hours (includes 4 hours calibration)
LOCATION CATEGORY:	SERVICE CENTER	SERVICE INVENTORY: N/A USED PARTS: SCRAP
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: October 2014
Calibration Required	PRODUCT LINE: WN AUTHOR: MF	
ADDITIONAL INFORMATION:		
Service Center: please reference Service Note N5230A-08		

© AGILENT TECHNOLOGIES, INC. 2012
 PRINTED IN U.S.A.

September 24, 2012

Rev. 20

**Agilent Technologies**

Situation:

Some network analyzers may require servicing. Only serial numbers listed on the previous page are affected.

Solution/Action:

Service Center personnel, please reference Service Note N5230A-08 for more detail.