

N5230A-09A**S E R V I C E N O T E**Supersedes:
N5230A-09**N5230A PNA-L Series Microwave Network Analyzers****Serial Numbers:**

See list at end of this Service Note.

Some network analyzers may require servicing. Only serial numbers listed are affected.**Parts Required:**

(Refer to Service Note N5230A-08A)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	ON SPECIFIED FAILURE	STANDARDS LABOR: 6.0 Hours (includes 4 hours calibration)
LOCATION CATEGORY:	SERVICE CENTER	SERVICE INVENTORY: N/A USED PARTS: SCRAP
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: October 2014
Calibration Required	PRODUCT LINE: WN AUTHOR: MF	
ADDITIONAL INFORMATION: N5230A-09 created 9/21/12. N5230A-09A created 10/31/12 to revise serial numbers. Service Center: please reference Service Note N5230A-08A		

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

October 31, 2012

Rev. 20

**Agilent Technologies**

Page 1 of 2

Situation:

Some network analyzers may require servicing. Only serial numbers listed on the previous page are affected.

Solution/Action:

Service Center personnel, please reference Service Note N5230A-08A for more detail.

Serial Numbers:

MY45000161
MY45000177
MY45000737
MY45000887
MY45000888
MY45000891
MY45001052
MY45001330
MY45001651
MY45001678
MY45001771
MY46400132
MY46400142
MY46400145
MY46400187
MY46400189
MY46400216
MY46400218
MY46400334
MY46400352
MY46400355
MY46400672
MY46401255
MY46401323
MY46401324
MY46401396
MY48100489
US43500180