

N8262A-01

Modification Recommended Service Note

Supersedes:
NONE

N8262A P-Series Modular Power Meter

Serial Numbers: MY55306002 / MY55490002

[Note 1: Not all instruments in this range are affected. Refer to Table 1 of this Service Note.]

Power Switch Wrong Orientation

Parts Required:

P/N	Description	Qty.
N8262-63003	PCA, Switch Board Assembly	1


ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	X AGREEABLE TIME	LABOR (REPAIR):	0.5 Hours (Average)		
		LABOR (CALIBRATION):	2 Hours (Average)		
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	X RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	X SERVICE CENTER		X SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	28 Feb 2017		
	X Calibration Required	PRODUCT LINE:	GM		
	<input type="checkbox"/> Calibration NOT Required	AUTHOR:	AT		

ADDITIONAL INFORMATION:

Situation:

The instruments identified in Table 1 of this Service Note have been manufactured with power switch wrong orientation. There is no long term electrical degradation from this power switch wrong orientation.



Solution/Action:

If an instrument identified on Table 1 of this Service Note is returned for calibration or repair, and this Service Note has not yet been applied, then the Power Switch will need to be replaced at that time.

To replace the Power Switch refer to the Keysight N8262A P-Series Modular Power Meter Service Guide at Front Panel Disassembly Instructions steps.

Affected instruments in the Serial Number range MY55306002 / MY55490002

The serial number range on the front page of this Service Note refers to instruments that were newly shipped, but only subsets of these were actually affected. The instruments listed in Table 1 are affected:

MY55306002	MY55306015	MY55306026	MY55386002
MY55306003	MY55306016	MY55306027	MY55386003
MY55306004	MY55306017	MY55306028	MY55386004
MY55306006	MY55306018	MY55316002	MY55386006
MY55306007	MY55306019	MY55316003	MY55476002
MY55306008	MY55306020	MY55326002	MY55476003
MY55306009	MY55306021	MY55326003	MY55476004
MY55306010	MY55306022	MY55326004	MY55476005
MY55306011	MY55306023	MY55326005	MY55476006
MY55306012	MY55306024	MY55366002	MY55480004
MY55306013	MY55306025	MY55376002	MY55490002

Table 1

Revision History:

Date	Service Note Revision	Author	Reason for Change
28 Feb 2016	01	Alvin Tan	As Published