

MODIFICATION RECOMMENDED

N8735A-01

S E R V I C E N O T E

Supersedes:
None

N8735A - DC POWER SUPPLY 30V, 100A, 5000W; GPIB, LAN, USB, LXI

The Product quality, reliability and specifications may be affected due to defective electrolytic capacitors in all N8700A 3300Watt & 5000Watt models.

Serial Numbers 11H1016A 11H0989B 11H0990B 11H0991A 11H0992A 11H1022A 11H1023A
RMA Number XW162 AXW115 AXW116 AXW113 AXW114 AXW150 AXW147

Parts Required:

P/N	Description	Qty.
NONE		

Situation:

This defect has been considered a product quality & reliability defect. The N8700A family uses many different value electronic capacitors and these capacitors are used on virtually every assembly in the instrument SPD cannot anticipate every possible specification impacted, and every possible defect type. SPD will assume that all specifications could potentially be impacted if the capacitors became defective or went out of specification.

Solution/Action:

For the Model & serial number described above arrangements should be made to have the product Serviced. It is recommended that action be taken as soon as possible. Taking immediate action will avoid a product defect.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 3.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: (Always)	
AUTHOR:	cp	PRODUCT LINE: SP	
ADDITIONAL INFORMATION: There has been an (Return Material Authorization) RMA number assigned. See above for the specific RMA corresponding to the model and serial number shown. Having the RMA number will expedite the repair process. Due to space RMA was not included in the above numbers. IE RMAXW000.			

© AGILENT TECHNOLOGIES, INC. 2011
PRINTED IN U.S.A.

November 14, 2011

Rev. 18

