

1111A-1A

SERVICE NOTE

SUPERSEDES:

1111A-1

HP MODEL 1111A AMPLIFIER

ALL SERIALS

PREFERRED REPLACEMENT FOR A2CR7 AND A2R16

The preferred replacement zener diode (A2CR7) and resistor (A2R16) are HP part numbers 1902-1173 and 0684-1021 respectively. This change provides for the use of a conventional low noise zener diode.

Make the appropriate changes to the Operating and Service Manual.

DM/bw

5/70-08

HEWLETT  PACKARD

For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 677-0400 • South (404) 436-6181
West (213) 677-3282. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, 1217 Meyrin-Geneva

Printed in U.S.A.