INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

1153A-01

SERVICE NOTE

Supersedes: NONE

1153A – Differential Probe

Serial Numbers: [0000A00000 / 9999Z99999]

Performance Verification Testing Procedure not in Manual. Use the Procedures in the 1141A manual.

Parts Required:

P/N Description Qty.

01141-90902 1141A Manual

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: [initials] PRODUCT LINE: [product line]

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2001 PRINTED IN U.S.A.

Agilent Technologies

January 14, 2002

Page 2 of 2 [SN number here]

Situation:

The 1153A probe User's Guide does not contain Performance Verification Procedures. The 1141A probe is the same probe but with a BNC interface instead of Infiniium. Testing procedures in this manual are the same as for the 1153A.

Solution/Action:

Use the testing procedures in the 1141A manual for Performance verification tests. Only change is to use an Infiniium scope in the procedures.