A MODIFICATION ONLY - DOES NOT COMMUNICATE

4142B-15

SERVICE NOTE

Supersedes: NONE

4142B Modular DC Source/Monitor

Serial Numbers: 0000A0000/9999Z99999

Replacement of BNC-to-Dual Banana Plug Cable for PV

Parts Required:

P/N Description Qty. 04142-61601 BNC-to-dual banana cable 1

Situation:

Agilent part number 11001-66001 BNC-to-dual banana cable, which is used in the performance verification test, is discontinued.

Solution/Action:

The replacement of the p/n 11001-66001 is 04142-61601. Note that this must be used for 4142B support purpose only.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: SY PRODUCT LINE: 1H

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES 2004 PRINTED IN U.S.A.



Agilent Technologies

July 9, 2004