S E R V I C E N O T E

SUPERSEDES: None

4155B Semiconductor Parametric Analyzer

Serial Numbers: See below.

Flexible Disk Drive Change

Duplicate Service Notes:

4155B-06 Serial Numbers: 0000A00000/9999Z99999 4156B-06 Serial Numbers: 0000A00000/9999Z99999

To Be Performed By: Agilent-Qualified Personnel

Parts Required: See text.

Situation:

The flexible disk drive (P/N 0950-3109) for the 4155B, 4156B was changed.

Continued

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
	INFORMATION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:		
TW	3300			

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 4155B-06

Solution / Action:

The replacement of 0950-3109 is 0950-2782. The 4155Bs, 4156Bs with the following serial numbers are shipped with the new FDD (0950-2782):

4155B: JP10E00303 and above 4156B: JP10E00342 and above

The FDD cover, the FDD cable, and the Front panel were also changed to fit the new FDD:

4155B:

	0000A00000/JP10E00302	JP10E00303/9999Z99999
FDD	0950-3109	0950-2782
FDD Cover	04155-04053	04155-04056
FDD Cable	04155-61620	04155-61615
Front Panel	04155-65141	04155-65151

4156B:

	0000A00000/JP10E00341	JP10E00342/9999Z99999
FDD	0950-3109	0950-2782
FDD Cover	04155-04053	04155-04056
FDD Cable	04155-61620	04155-61615
Front Panel	04155-65141	04155-65151