# S E R V I C E N O T E

SUPERSEDES: NONE

# 54540A Oscilloscope

**Serial Numbers:** 3339A00100 / US34360450

Elimination of two kits called out in the Service Manual parts list.

### **Duplicate Service Notes:**

54520A-01

54520C-01

54522A-01

54522C-01

54540A-01

54540C-01

54542A-01

54542C-01

#### **Situation:**

Kit numbers 5062-7397 and 5062-7398 are being replaced with the individual parts contained within the kits.

Continued

DATE: June 1995

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:	
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
TG	0800	The service manual will be updated to reflect the above changes.

© 1995 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## **Solution/Action:**

Kit 5062-7397 (MP14) is being replaced by the following individual parts:

Part Number	Description
54542-04101	Bottom Plate
54542-04102	Top Plate
54542-22401	Heatsink Standoff
0515-1908	Screw-Machine M2/0.4

Kit 5062-7398 (MP15) is being replaced by the following individual parts:

Part Number	Description
54542-21101	Heatsink
54542-09101	Heatsink Spring