## E3102B-03

# S E R V I C E N O T E

Supersedes:NONE

#### 4072B Advanced Parametric Tester

#### **Serial Numbers:**

E3102A	JP40G20687/JP40G20696
E3102L	JP10H90245/JP10H90246
E3102B	JP10L00300/JP10L00316
E3103A	JP30H30390/JP30H30401
E3103B	JP10L10269/JP10L10295

# Bundle E3160-61691 USB Extension Cable, and it may cause keyboard/mouse hang-up.

#### **Duplicate Service Notes:**

E3102A-07 E3103A-06 E3103B-04

Parts Required: None

#### **Situation:**

We already stop to bundle E3160-61691 USB Extension Cable because it is not necessary for tester installation requirement. But, E3160-61691 has shipped with applicable S/N of 4070. If install it, keyboard/mouse of system controller may hang-up.

#### **Solution/Action:**

Cast away E3160-61691, and do not install it.

If you need USB extension cable, use repeater type one. (Do not use HUB type.) But we don't recommend extending USB cable.

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

### **INFORMATION ONLY**

AUTHOR: JI PRODUCT LINE: 1H

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006 PRINTED IN U.S.A.

