MFORMATION ONLY-DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

E4422B-06

SERVICE NOTE

Supersedes: NONE

ESG "B" Signal Generator E4422B

Serial Numbers: 0000A0000 / 9999Z9999

The ESG-A and ESG-D series products are still maintaining the E4400-60180 (A12) board assembly and E4400-69180 exchange assembly. No board change or replacement has occurred.

Parts Required:

P/N: E4400-60180 / 69180 Description: Synthesizer Bd Assembly Qty. 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: SR PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004 PRINTED IN U.S.A.



March 1, 2004

Page 2 of 2 E4422B-06

Situation:

The E4400-60180 (A12) Synthesizer Board Assembly and the E4400-69180 Exchange Assembly are still being used in the ESG-B Family of Signal Generators, specifically the ESG-A and ESG-D series. Although there is a board replacement for the E4406A product line, this does NOT affect the ESG-B products.

Solution/Action:

Should a Synthesizer Board Assembly replacement occur, the replacement part number is either the E4400-60180 or E4400-69180. Users should still be able to obtain these as a replacement part.