

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E4423B-06B

S E R V I C E N O T E

Supersedes:
E4423B-06A

E4423B with options UNB or H99

Serial Numbers: [0000A00000 / 9999Z99999]

Mechanical attenuator, part number 33322-60014, with serial numbers less than 06400 (Made in USA) used in the identified products is susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions.

Parts Required:

P/N	Description	Qty.
33322-60014	Mechanical Attenuator	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: HLU PRODUCT LINE: 15

ADDITIONAL INFORMATION:

33322-60014 assemblies are to be provided at no cost until 1AUG2006..

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



July 18, 2005

Situation:

Mechanical attenuator, part number 33322-60014, with serial numbers less than 06400 (Made in USA) used in the identified products is susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions.

Solution/Action:

Mechanical attenuators, part number 33322-60014, will be provided for repair of products with less than 3 million attenuator cycles. Customers are responsible for labor and calibration charges.