

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E4432B-06

S E R V I C E N O T E

Supersedes:
NONE

ESG “B” Signal Generator E4432B

Serial Numbers: 0000A0000 / 9999Z9999

The ESG-A and ESG-D series products are still maintaining the E4400-60180 (A12) board assembly and E4400-69180 exchange assembly. No board change or replacement has occurred.

Parts Required:

P/N: E4400-60180 / 69180

Description : Synthesizer Bd Assembly

Qty. 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: SR PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.

March 1, 2004



Agilent Technologies

Situation:

The E4400-60180 (A12) Synthesizer Board Assembly and the E4400-69180 Exchange Assembly are still being used in the ESG-B Family of Signal Generators, specifically the ESG-A and ESG-D series. Although there is a board replacement for the E4406A product line, this does NOT affect the ESG-B products.

Solution/Action:

Should a Synthesizer Board Assembly replacement occur, the replacement part number is either the E4400-60180 or E4400-69180. Users should still be able to obtain these as a replacement part.