

N5181B-07

Information Only Service Note

Supersedes:
NONE

N5181B X-Series MXG Analog Signal Generator

Serial Numbers: Prefix from MY51350001 - MY57279999

The Problem – Front Panel Replacement Kit in light color no longer available

Parts Required:

P/N	Description	Qty.
N5180-60470	Front Panel Replacement Kit	1

ADMINISTRATIVE INFORMATION

Calibration Required
X Calibration NOT Required

PRODUCT LINE: PL15
AUTHOR: PY

ADDITIONAL INFORMATION:

Situation:

The Front Panel Replacement Kit, N5180-60441 which comes in the light gray color is no longer available to order due to our supplier no longer able to support us with the lower level module (LLM) for the kit.

Solution/Action:

The exact replacement is the dark gray color replacement kit, N5180-60470.

Listed below are the other part numbers in dark gray color if you would like to change the overall outlook of the instrument.

Description	Part Number
Instrument Outer Cover	N5180-00038
Strap Handle Assembly	N5180-60287
Hole Plug, Instrument Cover Side (2 required)	N9020-40014
Rear Panel Foot (4 required)	5041-7903
Bottom Foot (4 required)	5041-7906
Hole Plug, Bottom Feet (4 required)	N9020-40007
Front Panel Side Trim (2 required)	5042-8425

Revision History:

Date	Service Note Revision	Author	Reason for Change
2 Dec 2022	01	Petrina Yong	As Published