

S E R V I C E N O T E

SUPERSEDES: None

70004A Display

Serial Numbers: 0000A00000 / 3040A01050

Right Side Strap Handle does Not Meet Safety Standards**To Be Performed By:** Agilent-Qualified Personnel or Customer**Parts Required:**

P/N	Description
70004-60032	Side Strap Handle Replacement Kit

Situation:

The 70004A Display right side strap handle, situated on the side of the 70004A which accepts modules, may not support the weight of certain configurations. The right side strap handle must be removed from all 70004As.

Solution:

Order the right side strap handle replacement kit. Remove the right side strap handle and replace it with two beveled washers and two screws as provided in the Side Strap Handle Replacement Kit. See the installation note provided in the kit for proper location of the special beveled washers.

DATE: 25 June 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
SAFETY			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: SJR/RDS	ENTITY: 5300	AGILENT RESPONSIBLE UNTIL: ALWAYS	
		ADDITIONAL INFORMATION:	