

MODIFICATION RECOMMENDED – CORRECTS MANUFACTURING DEFECT

**N8975A-05**

**S E R V I C E N O T E**

Supersedes:  
None

N8975A

Serial Numbers Malaysia Manufactured: MY45270108, MY45270176, MY45270178,  
MY45270183, MY45270192-MY45270334

Serial Numbers Singapore Manufactured: SG45270113-SG45270126

**Some recent Agilent Noise Figure analyzers were shipped with “10 MHz REF OUT and IN” label inverted on the rear panel.**

**To Be Performed By: Customer**

**Parts Required:**

P/N	Description	Qty.
5190-0023	“10 MHz REF OUT and IN” Label	1

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.0 Hours		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of GMS period			
AUTHOR: DC	PRODUCT LINE: 12				


© AGILENT TECHNOLOGIES, INC. 2006  
PRINTED IN U.S.A.

October 2, 2006



**Situation:**

If the current label on your NFA looks like the one in the picture below, follow the solution/action item listed in the next picture.



**Solution/Action:**

Adhere the “10 MHz REF OUT and IN” label on top of the old label as shown below.

